Date: 12/11/00

For the Repair of the PROM/RAM Type 6 CCA NSN: 5998-01-334-9366 P/N: 247687-101; CAGE: 13973

SOW-03-844-1-8E099B-2/1

- 1. This SOW identifies the work effort that shall be performed by the Contractor to rebuild the PROM/RAM Type 6 CCA; NSN 5998-01-334-9366; P/N 247687-101; CAGE 13973.
- 2. The attached manuscript has been reviewed and is concurred upon by the following signers:

HARVEY C. DEARING

Weapon System/Equipment Manager Data Systems Section (Code 844-1) MCLB, Albany GA

GYSGT R. WRIGHT

Equipment Specialist Data Systems Section (Code 844-1) MCLB, Albany GA STEPHANIE BYRD

Inventory Manager Data Systems Section (Code 844-1) MCLB, Albany GA

TABLE OF CONTENTS

<u>Paragraph</u>	<u>Title</u>	<u>Page</u>
1.0	Scope	1
1.1	Background	1
2.0	Applicable Documents	1
2.1	Military Standards	1
2.2	Other Government Documents and Publications	1
2.3	Industry Standards	2
3.0	Requirements	2
3.1	General Tasks	2
3.2	Detail Tasks	2
3.2.1	Phase I (Pre-Induction)	3
3.2.2	Phase II (Repair)	3
3.2.3	Phase III (Inspection, Testing and Acceptance)	3
3.2.4	Phase IV (Packaging, Handling, Storage and Transportation (PHS&T)	4
3.3	Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM)	4
3.4	Contractor Furnished Materiel (CFM)	4
3.5	Electrostatic Discharge (ESD) Control Program	4
3.6	Quality Assurance Provisions	4
3.7	Acceptance	5
3.8	Rejection	5
3.9	Configuration Control	5
4.0	Reports	5
4.1	Pre-Induction Checklist	5
4.2	Test/Inspection Report	5
4.3	Repairable Item Inspection Report	5
4.4	Monthly Progress Report	5
<u>Appendix</u>		
A	Standard Form 364 (Rev. 2-80)	A-1

STATEMENT OF WORK FOR THE Inspect Repair Only As Necessary (IROAN) of PROM/RAM Type 6 CCA (5998-01-334-9366) P/N: 247687-101; CAGE: 13973

1.0 Scope. This Statement of Work (SOW) establishes, sets forth tasks, and identifies the work effort that shall be performed by the Contractor to IROAN the PROM/RAM Type 6 CCA, 5998-01-334-9366; hereafter referred to as the PROM/RAM TYPE 6 CCA. The PROM/RAM TYPE 6 CCA, Drawing Number 247687, CAGE 13973, is a component of the Tactical Air Operations Module (TAOM), AN/TYQ-23(V)1. This document contains requirements to restore the PROM/RAM TYPE 6 CCA to Condition Code "A". Condition Code A is defined as "serviceable/issuable without qualification, new, used, repaired or reconditioned material which is serviceable and issuable to all customers without limitation or restriction, including material with more than six months shelf-life remaining."

- **1.1 <u>Background</u>:** IROAN is defined as "That maintenance technique which determines the minimum repairs necessary to restore equipment components or assemblies to prescribed maintenance serviceability standards by utilizing all available diagnostic equipment and test procedures in order to minimize disassembly and parts replacement."
- **2.0** <u>Applicable Documents</u>. The following documents form a part of this SOW to the extent specified. Unless otherwise specified, the issues of these documents are those listed in the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto which is in effect on the date of solicitation. In the event of conflict between the documents referenced herein and the contents of this SOW, the contents of this SOW shall be the superseding requirement.

2.1 Military Standards.

MIL-STD-129 DoD Standard Practice for Military Marking

MIL-STD-2073-1D DoD Standard Practice for Military Packaging

2.2 Other Government Documents and Publications: The issues of those documents cited below shall be used.

TM-08565A-24P/9 AN/TYQ-23(V)1 Illustrated Parts Breakdown Manual

247687 Parts List, 32K x 32K Prom High Density CCA

247687-720 Test Specifications

247687-750 Test Procedures

DoD 4000.25-1-M MILSTRIP Manual

NAVICPINST 4491.2A Requisitioning of Contractor Furnished Materiel from the

Federal Supply System

Military Handbooks (For Guidance)

MIL-HDBK-61 Configuration Management

2.3 <u>Industry Standards</u>

JESD625-A Requirements for Handling Electrostatic-Discharge

Sensitive ESDS Devices

ANSI/ISO/ASQC Q9003-1994 Quality Systems-Model for Quality Assurance in Final

Inspection and Test

Industry Standards (For Guidance)

ANSI/EIA-649 National Consensus Standard for Configuration

Management

Copies of Military Standards and Specifications are available from the DOD Single Stock Point, Document Automation and Production Service, Building 4/D, 700 Robbins Avenue, Philadelphia, PA 19111-5094, Telephone (215) 697- 2179 or DSN 442-2179, or http://www.dodssp.daps.mil. Copies of other government documents and publications required by contractors in connection with specific SOW requirements shall be obtained through the Contracting Officer: Commander, Attn: Contracting Officer (Code 891), Marine Corps Logistics Bases, 814 Radford Blvd., Albany, Georgia 31704-1128, commercial telephone number (229) 639-6761 or DSN 567-6761. Copies of engineering drawings, if applicable, shall be obtained from Life Cycle Management Center, Attn: Code 851-3, 814 Radford Blvd. Suite 20320, Albany, Georgia 31704-0320, commercial telephone number (229) 639-6410 or DSN 567-6410.

3.0 Requirements

- **3.1** General Tasks: In fulfilling the specified requirements, the Contractor shall provide materials, labor, equipment, facilities and missing/repair parts, necessary to inspect, diagnose, restore, and test and calibrate the PROM/RAM TYPE 6 CCA. Upon completion of repairing the subject item it shall be Condition Code "A".
- **3.2** <u>Detail Tasks</u>: The following tasks describe the different phases for repair of the PROM/RAM TYPE 6 CCA:

Phase I Pre-Induction

Phase II Repair

Phase III Inspection, Testing and Acceptance

Phase IV Packaging, Handling, Storage and Transportation (PHS&T)

- **3.2.1** Phase I (Pre-Induction): A pre-induction inspection analysis shall be performed for each PROM/RAM TYPE 6 CCA within five working days of induction into the Contractor's facility for evaluation of repair capability. If repair is not feasible, assign Condition Code "H" (CC "H"), notify Marine Corps Logistics Base (MCLB/Code 844-1), Albany, Georgia for disposition instructions, otherwise assign CC "M" and induct into the repair cycle. The Pre-Induction Checklist (Appendix A) shall be used to report all anomalies and shall be provided to the government in accordance with section 4.0 of this SOW.
- **3.2.2** Phase II (Repair): After pre-induction tests and inspections have been completed, repair of the PROM/RAM TYPE 6 CCA shall be accomplished in accordance with this SOW. Deficiencies noted on the Pre-Induction Checklist during Phase I shall be repaired/replaced. Components or assemblies shall not be disassembled for replacement of parts unless that part has failed, or the component assembly wherein the part is located is disassembled for repair.

a. Hardware

- (1) Replace broken, unserviceable and/or missing hardware including nuts, bolts, screws, washers, turnlock fasteners, mandatory replacement items, safety, and one-time use items. Unserviceable would include any of the above that failed to function properly.
- (2) Ensure proper hardware locking devices are present on all moving mechanical assemblies.
- (3) Hardware normally supplied with commercial parts shall be used unless specifically prohibited.
- b. <u>Publications and Documentation:</u> In addition to the documents invoked in Section 3 of this SOW, the Contractor may use the following documents:

247687 Parts List, 32K x 32K Prom High Density CCA
247687-720 Test Specifications
247687-750 Test Procedures
TM-08565A-24P/9 AN/TYQ-23(V)1 Illustrated Parts Breakdown Manual

3.2.3 Phase III (Inspection, Testing and Acceptance)

- a. Inspection, Testing and Acceptance of the PROM/RAM TYPE 6 CCA shall be conducted in accordance with the documents and TM listed in paragraph 3.2.2.b and documentation retained by the manufacturer.
- b. The Contractor shall be responsible for correcting any deficiencies identified during inspection/testing. MCLB (Code 844-1), Albany, GA representatives may require the Contractor to repeat tests or portions thereof, if the original tests fail to demonstrate compliance with this SOW.

3.2.4 Phase IV (Packaging, Handling, Storage and Transportation (PHS&T)

- a. The Contractor shall be responsible for preservation and packaging of items being repaired under the terms of this statement of work. Items being prepared for long term storage or shipment to overseas destinations shall be in accordance with the level A requirements of MIL-STD-2073-1D, Appendix J, Table J.Ia., Specialized Preservation Code "GX". Items being prepared for domestic shipment and immediate use shall be to level B requirements. All items subject to damage by electrostatic discharge shall be packed into a reusable fast pack container.
 - b. Marking of all items shall be in accordance with MIL-STD-129.
- c. The Marine Corps will provide the contractor with the shipping address(es) for delivery of the repaired equipment. The contractor shall be responsible for arranging for shipment to the pre-designated site(s). The Marine Corps will be responsible for transportation costs associated with shipping the subject equipment to and from the Contractor.
- 3.3 Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM): GFE is government owned equipment authorized by contract for use by a commercial/government contractor. It is neither consumed during production nor incorporated into any product. GFM is materiel furnished to a contractor that will be consumed during the course of production or incorporated into product being manufactured/remanufactured under a contract/statement of work. In the event the Contractor has GFE/GFM requirements, the Management Control Activity (MCA/Code 827-2), Marine Corps Logistics Bases, Albany, Georgia, will coordinate required GFE and will maintain a central control on Marine Corps assets in the Contractor's possession. The MCA will forward a GFE Accountability agreement to the Contractor Facility for signature to establish a chain of custody and property responsibilities for Marine Corps assets. The Contractor shall report receipt of all GFM and report consumption of GFM to the MCA.
- **3.4** Contractor Furnished Materiel (CFM): The Marine Corps has adopted the Navy's procedures regarding Contractor Furnished Materiel (NAVICPINST 4491.2A). In the event that Contractor Furnished Materiel is required for repair parts, the contractor shall requisition through the DOD Supply System. DOD 4000.25-1-M, (MILSTRIP) Chapter 11 authorizes contractors to requisition through the DoD Supply System.
- **3.5** Electrostatic Discharge (ESD) Control Program: The contractor shall establish, implement and document an ESD control program following the guidelines provided in JESD625-A. ESD protective measures shall be used during manufacturing, handling, inspection, test, marking, packaging, storing and transporting ESD sensitive components.
- **3.6 Quality Assurance Provisions:** The Contractor shall provide and maintain a Quality System that as a minimum, adheres to the requirements of ANSI/ISO/ASQC Q9003-1994, Quality System Model for Quality Assurance in Final Inspection and Test. The program shall ensure quality throughout all areas to include processing, assembly, inspection, test, maintenance, and preparation for delivery and shipping. Unless otherwise specified in the contract, the contractor shall be responsible for performance of all inspection requirements. The

Government (MCLBA/Code 844-1) reserves the right to perform any of the inspections set forth in the contract where such inspections are deemed necessary to assure products and services conform to the prescribed requirements.

- **3.7** Acceptance: The performance of the Contractor and the quality of work delivered, including all equipment furnished and documentation written or compiled, shall be subject to inprocess review and inspection during performance. Inspection may be accomplished in-plant or at any work site or location, and Marine Corps (Code 844-1) representatives shall be permitted to observe the work or to conduct an inspection.
- **3.8** Rejection: Failure to comply with any of the specified requirements listed herein shall be reason for rejection by MCLB Code 844-1, Albany, representative. The Contractor shall, at no additional cost to MCLB, Albany, Georgia, correct the deficiencies and repeat the verification until an acceptable compliance with acceptance test procedures is demonstrated.
- **3.9 Configuration Control:** The contractor shall apply configuration control procedures to established configuration items. The contractor shall not implement configuration changes to an item's documented performance or design characteristics without prior written authorization. If it is necessary to temporarily depart from the authorized configuration, the contractor shall prepare and submit a Request for Deviation. MIL-HDBK-61 (paragraph 4.3 and Table 4-9) and ANSI/EIA-649 (paragraph 5.3.4) provide guidance for preparing this configuration control document.
- **4.0** Reports: All report deliverables shall be submitted in hard copy to Commander (Code 844-1), Marine Corps Logistics Bases, 814 Radford Blvd. Suite 20320, Albany, Georgia 31704-0320, unless directed otherwise in a Contract Data Requirements List.
- **4.1** <u>Pre-Induction Checklist</u>: The Contractor shall complete the Pre-Induction Inspection Checklist (Appendix A) for each PROM/RAM TYPE 6 CCA repaired. These documents shall be available prior to final acceptance testing. One copy of each document shall be provided to MCLB (Code 844-1) Albany, Georgia, within 30 days after final acceptance of the PROM/RAM TYPE 6 CCA.
- **4.2** <u>Test/Inspection Report</u>: The Contractor shall provide a Test/Inspection for each PROM/RAM TYPE 6 CCA.
- **4.3** Repairable Item Inspection Report: The Contractor shall provide a Repairable Item Inspection Report for each PROM/RAM TYPE 6 CCA. The report shall be identified by United States Marine Corps Serial Number.
- **4.4 Monthly Progress Report:** The Contractor shall provide a Monthly Progress Report summarizing the progress and status of the PROM/RAM TYPE 6 CCA Program.

INSTRUCTIONS

DEPARTMENT OF DEFENSE: DLAR 4140.55/AR 735.11.2/NAVSUPINST 4440.127F/AFR 400.54/MCO 4430.3E, Reporting of Item and Packaging Discrepancies, and/or DLAR 4140.60/AR 12-12/NAVSUPINST 4920.9B/AFR 67.7/MCO 4140.1B, processing Discrepancy Reports Against Foreign Military Sales Shipments. CIVILIAN AGENCIES: See FPMR handbook cited in 19 (2) (a).

REPORT OF DISCREPANCY (ROD) SHIPPING PACKAGE	1 DATE OF PREPARAT	ION	2 REPORT N	IUMBER				
3 TO (Name and Address, Include ZIP Code)	3 TO (Name and Address, Include ZIP Code)							
5a SHIPPERS NAME	Sh NUMBER AND DATE	E OF INVOICE		ORTATION DOCU	JMENT NUM	BER		
7a SHIPPER'S NUMBER (Purchuse Order/Shipmnet, Contract, etc)	75 OFFICE ADMINISTERING C	CONTRACT	·		8. REQUISITION etc.)	ER'S NÛMBER //	Requisition, Pu	rchase Request,
9 SHIPMENT, B	ILLING, AND RECEIPT DATA			10.	DISCREPA	NCY DATA		11
NSN/PART NUMBER AND NOMENCLATURE	UNIT OF ISSUE	QUANTI SHIPPED BILLED	RECEIVED	QUAN- TITY	UNIT PRICE (b)	TOTAL	CODE (d)	-
(a)	(b)	(c)	(d)	(a)	(0)	(c)	107	
12 REMARKS (continue on separate sheet of paper if necessary)	essarvi						<u> </u>	
12 Residence (Common on separate short of paper 9 need	adure gy							

15. DISTRIBUTION ADDRESSES FOR COPIES

364-103

7540-00-159-4442 (Previous edition is obsolete)

I DISCREPANCY CODES

STANDARD FORM 364 (Rev. 2-80) (EG) Prescribed by GSA FPMR 101-20-0

2 ACTION CODES

16 FROM		17 DISTRIBUTION ADDRESSEES FOR DISTRIBUT	ION
18. TO:			
		Use window enverthis document. In address, including starting one typing the left dot. Each a NOT extend bey Address must not be space typing.	nsert Name and ng ZIP Code, ng space below address line must cond right dot exceed four single ng lines.
19 IN ACCORD 3 MATERIAL DOCUMENT NU		DISCREPANCY ON FACE OF THIS FORM	VI:
HAS WILL BEEN BE SHIPPED		NO RECORD OF SHIPMENT RESUBMIT TO PROPER OFFICE UNDER	T REPORT
c AN ADJUSTMENT IN BILLING CREDIT HAS BEEN/WILL BE PROCESSED	DEBIT		ROOF OF LIVERY
f AN ADJUSTMENT IN BILLING FOR THIS REPORTED D THE INDICATED REGULATION	SCREPANCY WILL NOT BE PROC	ESSED FOR THE FOLLOWING REASON WHICH IS C	TITED IN
(1) REASON FOR NOT PROCESSING		(2) PRESCRIBING REG	
(a) DISCREPANCY WAS NOT REPORTED WITHIN THE TI AND/OR	IME FRAMES ALLOWED	(a) CHAPTER 5 OF THE GSA HANDBOOK DISCREPANCIES OR DEFICIENCIES IN GS DOD SHIPMENTS, MATERIALS, OR BILLIN (FPMR 101.26 8)	A OR
(b) DOLLAR VALUE DOES NOT MEET THE CRITERIA PRE OR AGREEMENT INDICATED IN 191(2)	SCRIBED IN THE REGULATION	(b) CHAPTER 2 AND/OR 7 OF DOD 4000 25. MILITARY STANDARD BILLING SYSTEM (MILBILLS) AND/OR DD 1513, U.S. DOD OFF ACCEPTANCE, AS APPLICABLE	
20. TH	E FOLLOWING DISPOSITION IS TO) BE MADE OF THE REFERENCED MATERIAL	
a PROCESS FOR DISPOSAL IN ACCORDANCE WITH SERVICE/AGENCY DIRECTIVES	b. REPRESENTATIVE DISPOSITION	WILL CALL FOR DISCUSSION CONCERNING	DAYS
RETAIN MATERIAL AT NO CHARGE	d. MATERIAL WILL	BE PICKED UP IN:	DAYS
e. SHIP MATERIAL Specify location)			
(I) GBL APPROPRIATION CHARGEABLE:			
(2) CHARGES COLLECT - VIA. FRI	EIGHT EXPRESS	PARCEL POST	-
(3) PARCEL POST LABEL ATTACHED	(4) FREIGHT PRE	PAID	
f OTHER (Specify)			<u> </u>
21 IF MATERIAL IS STILL REQUIRED.	22 REPLACEMENT W	TITH SATISFACTORY MATERIAL	DATE
23 REMARKS (Continue on separate sheet of paper if necessary).	WILL BE WADE O		
24a. TYPED OR PRINTED NAME AND PHONE NUMBER OF PREPARING OFFICIAL	24b. SIGNATURE		24c DATE
		STANDARD FORM 364 BACK	(REV. 2-80)

(1 Data Item)

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing date sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden, to Department of Delanse, Washington Headquarters Services, Directorate for Information Department of Delanse, Washington Headquarters Services, Directorate for Information Department of Delanse, Washington Devia Highway, Suita 1204, Altington, VA. 22202.4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid DMB control number. Please DO NOT RETURN your form to the above address. Send completed form to the Bovernment Issuing Contracting Officer for the Contractiff No. Issted in Block E.

	EM NO	B. EXHIBIT		C CATCOORY.						
A. CONTRACT LINE IT	LIN NU,	D. EXMISH		C. CATEGORY:	OTHE	R	×			
D. SYSTEM/ITEM					F. CONTR					
	AM Type 6 CC.	A	· · · · · · · · · · · · · · · · · ·	-						
DATA ITEM NO. 2	. TITLE OF DATA ITEM	<u></u>			3. SUBTITLE	- "				
A001	Contractor's Pr	ogress, Sta	tus, and Mar	agement Report			Manageme	ent		
. AUTHORITY (Data Acquisition	n Dacument No.)	-	, CONTRACT REFEREN).E		B. REDUIRIN				
	IGMT-80227			SOW 4.4			MCLB	A (844)	1	
DD 250 REQ .	DIST STATEMENT REQUIRED	10, FREQUENCY		12. DATE OF FIRST SUBMIS		14.	DISTRIBUTION	,		
APP CODE		IVI I	'HLY	See Blk 13. DATE OF SUBSEQUENT	16	_		L	b. COPIES	
AFF LUDE	Α	II. AS UF DATE		SUBMISSION	1.6	a.	ADORESSEE	Draft		inal
REMARKS	· · · · · · · · · · · · · · · · · · ·	!		See Blk	10	MCLB	À (844-1)	0	Reg 1	Нерго
ontractor forma	at is authorized.					WICLB	A (044-1)	├ ─~		^U
lk 4 - Tailor Dl) 3i, 10.3j, 10.	I-MGMT-80227 3k, and 10.3n.	as follows	: Delete para	graphs 10.3g, 1	0.3h,					
	orting period sha bmission shall b									
	ent submissions							 		\vdash
icn month.							·	1		1 1
istribution State	ement A: Appro	oved for m	blic release	distribution is u	nlimited					
	· · · · · · · · · · · · · · · ·			THE PERSON NAMED IN CO.						
								+		
						 				{
								1		
								├ ─		
								╂──┤		
						<u> </u>				├─┤
						 		 		\vdash
										
						J		 		
					!					
							·			
								 		
								├ ─		
					l	<u> </u>				
								 		
							· _ · · · · · · · · · · · · · · · · · ·	 		
						15. TOTAL		0	1	0
PREPARED BY			H. DATE	I. APPROVED I		-3. TUTAL		J. DATE		
11:10	11.74	2	· 1.1	110		-	ing	151	(22)	/F
Kan A. V	$\mathbf{Y} / (\mathbf{X} + \mathbf{M} \mathbf{M})$	A 1	12/11/00	1941/11	ヘット・ヘイ・	ייעע		1 ~1	///	/ /

(1 Data Item)

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and meintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services. Directorate for information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Suits 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstending any other provision of law, no person shall be subject to any penalty for falling to compty with a collection of information if it does not display a currently valid DMB control number.

Please DO NOT RETURN your form to the above address. Send completed form to the Government issuing Contracting Officer for the Contractific No. listed in Block E.

A. CONTRACT LINE	ITEM NO.	B. EXHIBI	т	C. CATEGORY:	DTHEF	X				j
D. SYSTEM/ITEM PROM/	RAM Type 6 CC	Δ	E. CONTRACT/PR							İ
1. DATA ITEM NO.	2. TITLE OF DATA ITEM				3. SUBTITLE					17. PRICE GROUP
B001	Repa	irable Ite	m Inspection 1	Report	Inte	grated Logistics Su	pport Si	tandar	ds	
	tition Document No.)		_	VCE	1	6. REQUIRING OFFICE		18. ESTIMATED TOTAL PRICE		
		10 FREATIFIE	CY		AN	 	IA (844)) ——-		1
LT	REQUIRED	1				14. DISTRIBUTION		h COPIES		
8. APP CODE	-	11. AS OF DA	TE	13. DATE OF SUBSECUENT		a. Addressee				
	A			See Blk 1	6		<u> </u>	Reg	Repro	}
Contractor for	mat is authorized.						1 0	1	0	
Blk 10 - A sepa repaired.	arate report shall	be submi	tted for each F	PROM/RAM Type	6 CCA				ļ -	
Blks 12 & 13 - completion of 6	Submit report by each PROM/RAM	Marine (I Type 6	Corps Serial N CCA.	lumber 30 days af	ter					
							1			
TO: 4 11 41 04										
Distribution Sta	atement A: Appr	oved for	public release,	, distribution is un	limited.					
:										
						<u> </u>				
							ļ			.1
						<u> </u>	-			
							<u> </u>			
										'
										:
						<u> </u>			1	i
										:
							1			1
										!
										1
						LE TATAL				
G. PREPARED BY			H. DATE	I. APPROVED BY	1	19. 101AL			<u> </u>	;
SYSTEMATION PROMIRAM Type 6 CCA SAME TO A SUBSTITUTE TO THE PROMIRAM TYPE 6 CCA SAME TO THE SAME TO THE SAME										
DD FORM 1423-1	, AUG 96 (EG)	7		EVIOUS EDITION MAY BE L	JSED.		Page	_ of	Pages	•

(1 Data Item)

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Suits 1204, Arlington, VA 22202-4302, Respondents should be aware that notwithstanding any other provision of law, no person abid bis subject to any penalty for felling to comply with a collection of information if it does not display a currently valid OMB control number. Please 00 NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the ContractIPR No. Issted in Black E.

A. CONTRACT LINE	EITEM NO.	B. EXHIBIT	T	C. CATEGORY:		r ×				
). SYSTEM/ITEM			E. CONTRACT/		F. CONTR					
	/RAM Type 6 C	CA	L. CONTRACTA	rn My,	r. CUMIN	ACTUR				
DATA ITEM NO.	Z. TITLE OF DATA ITEM				3. SUBTITLE		-			
B002		Test/Insp	ection Repo	rts	No	nDestructive Testing	and In	spectio	on	
AUTHORITY (Data Acqu	isition Document No.)		5. CONTRACT REFER			8. REQUIRING OFFICE		- P		
DI	-NDTI-80809B			SOW 4.2		MCLE	A (844))		
DD 250 REQ	9. DIST STATEMENT REQUIRED	10. FREQUENC		12. DATE OF FIRST SUBM	SSION	14. DISTRIBUTION				
DD	- NEUGINEO	A	SREQ	See Bll	: 16		Ţ <u> </u>	b. COPIES		
APP CODE		11. AS OF DAT		13. DATE OF SUBSEQUENT SUBMISSION	,	n AODRESSEE	a AODRESSEE			
	A	A	SREQ	See Bl	: 16		Draft	Reg	ag Repro	
REMARKS Ontractor for	mat is authorized	1.				MCLBA (844-1)	0	1	(
						DCMAO 0 1				
k 12 - Suom Sceptance Te	nt test report with esting. DCMAO	um 30 days will review	s after compl v and provide	etion of Producti e comments to M tance/nonaccepta ations/comments	on CLBA					
thin 30 days	of receipt. MCI	LBA will p	rovide accep	tance/nonaccepta	nce to the					
CMAO.	umi 50 days anei	receipt of	recommend	auons/comments	irom					
ys of receip	t. This review/ap	proval cyc	le shall be re	ment comments we peated until the C	ontractor		4			
eives appro	oval from the Gov	vernmenf.		•	·					
stribution St	tatement A: Appi	roved for p	ublic release	, distribution is u	nlimited.		4			
							 			
							+			
							 			
						ļ	 			
							1			
							1			
							<u> </u>			
							1 1			
							 			
							1			
							11		-	
							1 1			
							1			
							<u> </u>			
						-				
DEDARES DE			1			15. TOTAL	0	2	0	
REPARED BY	_		H. DATE	I. APPROVED	ВҮ		J. DATE			
410	LI) Ar	H	12/11/0	186	C	(1)	۱	, /	_	
	Y J A A///\									

(1 Data Item)

Form Approved

OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to everage 110 hours per response, including the time for reviewing instructions, searching existing data sources, gethering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Department and Reports (0701-0198), 1215 Lefferson Devis Highway, Suite 1204, Ariington, VA 22202-4302. Respondents should be aware that netwithstanding any other provision of law, no person shell be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. Please DO NOT RETURN your form to the above address. Send completed form to the Sovernment Issuing Contracting Officer for the Contractiffs No. Islaed in Block E

	ntracting officer for the Contract/	4								
A. CONTRACT LINE	ITEM NO.	B. EXHIBIT C. CATEGORY:			OTHER					
D. SYSTEM/ITEM		1				ACTOR				
	RAM Type 6 CC	<u> </u>								
1. DATA ITEM NO.	2. TITLE OF DATA ITEM				3. SUBTITLE					
C001		Request	For Deviation	1		Configuration Mar	nageme	nt	- 1	
4. AUTHORITY (Data Acquis			5. CONTRACT REFERE			6. REQUIRING OFFICE				
	CMAN-80640C			SOW 3.9		MCLBA	4 (851)	<u> </u>		
7. DD 250 REQ LT	9. DIST STATEMENT REQUIRED	10. FREQUENC	SREQ	12. DATE OF FIRST SUBMISS SEE BLK		14. DISTRIBUTION	1	b. COPIES		
8. APP CODE	A	11. AS OF DAT	TE	13. DATE OF SUBSEQUENT SUBMISSION		a. ADDRESSEE	Draft	<u> </u>	nai	
16 OFMADVO		<u> </u>				7 (OLD) (OS1 (A)	+ +	Reg	Repro	
	ctor format in .do					MCLBA (851-2)	0	1	0	
Blks 10 & 12 - nonconforming documentation.	RFDs shall be su material which o	ibmitted to loes not n	o obtain autho neet prescribe	orization to deliver d configuration	r					
RFDs will be receipt by the (reviewed and disp Government.	osition de	termined with	nin 30 calendar da	ys upon					
RFDs shall be mbmatcomcont	submitted via e-π figmngmnt@matc	nail to the om.usmc.	following add mil	dress:						
Distribution Sta	atement A: Appr	oved for	public release	, distribution is ur	nlimited					
							1			
							 			
							├			
						<u> </u>	}	<u> </u>		
							 			
							1			
							 			
							-			
							 			
						<u> </u>				
						15. TOTAL	0	1	0	
G. PREPARED BY	10 A =		H. DATE	I. APPROVED B	Ϋ́		J. DATE		\neg	
Landr	ice Eclese	un.	300ct	DD Afon	ula C	Dearing	122	1///	~ \	
7 3 5 7 7 7	<u> </u>			~ / I (///		- JULYVIY	10-1	<u> </u>		

17. PRICE GROUP

18. ESTIMATED

TOTAL PRICE

DD FORM 1423-1, AUG 96 (EG)

PREVIOUS EDITION MAY BE USED.

Page of Pages
Designed using Perform Pro, WHS/DIOR, Aug 98